


Switched (RCM-O) Connectivity Diagram

Switched



Temperature Sensor



Temperature, Humidity, & Dew Point Sensor



RSD Remote Display

Static IP Address for set-up and configuration

Optional Remote Sensors Connect via RJ12