

# Power Monitoring PLUS (RSM) Connectivity Diagram

Optional Remote Sensors - Connect via I/O Port



Door Position Sensor



Smoke Alarm Kit




Water Sensor



City Power Monitor

Power Monitoring - Plus



Temperature Sensor



Temperature, Humidity, & Dew Point Sensor



RSD Remote Display



DLink® Web Enabled Camera

Static IP Address for set-up and configuration

Optional Remote Sensors Connect via RJ12